

OFFICE OF THE ASSISTANT EXECUTIVE ENGINEER,
BRAJRAJNAGAR (R&B) SUB. DIVISION


No. 219 //Dt. 3/6/2021

BUILDING SAFETY CERTIFICATE

Certified that Ghanshyam Hemlata Vidya Mandir, Balijori, Debadahi, Jharsuguda situated at Balijori, Debadahi, Jharsuguda in Ward No.13, within Jharsuguda Municipality area. They have constructed the School Building on their own land. The school building has constructed having pucca Boundary wall of the school, with stair cases as per rule, Long and clear corridor, Ground floor with ramp facility, spacious and sufficient class-rooms with 02 (Two) Auditorium.

Necessary Proforma No.01 & 02 is enclosed herewith for your information & further necessary action.

Office Seal.

Signature with Seal: 
Name: Ashish Kumar Kenka
Designation: Assistant Executive Engineer.
03.06.2021
Assistant Executive Engineer
Brajrajnagar (R&B) Sub-Division

PROFORMA FOR THE SAFETY CERTIFICATE OF SCHOOL BUILDING

(PART-I)

(To be filled by the head by the School, Institute)

1. Name of the School : Ghanshyam Hemlata Vidya Mandir
2. Location : Balijori, Debadhi, Jharsuguda
3. Plot Area : 39,801 Sq Mtrs
4. Plinth Area : 6803 Sq Mtrs
5. Number of Stories : Tripple Stories
6. Area of Constructed part of the building : 6803 Sq Mtrs
7. If the building has been constructed under the supervision of the qualified Engineer, the following details may be given:-
 - a) Name of Engineer with Qualification : Ashish Kumar Lenka (Asst. Executive Engg.)
 - b) Address of the Engineer : Brajrajnagar
 - c) If structural drawing used in construction : Yes
 - d) Name & address of Architect with Qualification. : Mr. Ram Ratan Agrawal, Aditya Techno Engineers Sarbahal, Jharsuguda
8. Whether the building has been constructed for the purpose of:
 - a) School : Yes / No
 - b) Residential purpose and use for a School : Yes / No
9. Materials used for Roofs.
 - a) RCC Slabs : Yes / No
 - b) RS Joists & Bottom : Yes / No
 - c) Wooden Joints and Bottom : Yes / No
10. Material used for Walls
 - a) Mud Mortar : Yes / No
 - b) Cement Mortar : Yes / No
 - c) Lime Mortar : Yes / No
11. Flooring
 - a) Conglomerate : Yes / No
 - b) Terrace : Yes / No
 - c) Brick Paving : Yes / No
12. A detailed drawing indicating the doors along with windows and location fitting and windows is attached.

Signature of the Head of School/ Institute

Principal
Ghanshyam Hemlata Vidya Mandir
Jharsuguda

(PART-II)

(To be filled by the SDE)

I have visited the above mentioned school on dated 01.06.2021 and have visually inspected it from all angles of safety and find it fit for normal use as school building.

In case any addition/alteration or expansion and modifications to this building is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be re-obtained after the completion from the undersigned.

In case the building is affected by flood or if there is settlement of walls/foundations or sagging of roofs etc. Immediate inspection of the undersigned be arranged to check the stability and safe of the building.

This building can be safely occupied for normal use up to (indicate which it can be used) 31.05.2022.


Sub Divisional Engineer.

03.6.2021
Assistant Executive Engineer
Brajrajnagar (R&B) Sub-Division